



## TOTAL TRUCK CARE

Love's Travel Stops & Country Stores, Inc. D/B/A  
LOVE'S  
0563 St Clairsville, OH SPEEDC  
66320 Belmont-Morristown Rd BELMONT , OH  
(740) 330-6000

INVOICE # : 4009135263  
WORK ORDER DATE : 03/04/2026  
CLOSE DATE : 03/04/2026  
SERVICE TYPE : Roadside

SHIP TO : JS Transportation LLC(3563024)  
9327 Woodend Rd  
Edwardsville , KS 66111-1709  
(913) 422-6657-1

SOLD TO : JS Transportation LLC(3563024)  
9327 Woodend Rd  
Edwardsville , KS 66111-1709

BILL TO : JS TRANSPORTATION LLC(49005761)  
9327 WOODEND ROAD  
KANSAS CITY , KS 66111  
ACCOUNT # : 214701

|                                     |           |                    |                   |           |                   |               |                |
|-------------------------------------|-----------|--------------------|-------------------|-----------|-------------------|---------------|----------------|
| <input type="checkbox"/>            | TRACTOR # | VIN #              | YEAR              | MAKE      | MILEAGE           | PLATE#/STATE  | ENGINE         |
|                                     | 1015      | 1XPBDP9X5KD629883  | 2019              | PETERBILT | 839235            | 233920/KS     | PACCAR         |
| <input checked="" type="checkbox"/> | TRAILER # | VIN #              | YEAR              | MAKE      | HUBOMETER         | PLATE#/STATE  | REEFER #       |
|                                     | H14011    | 5V8VC5325TM601132  | 2026              | OTHER     |                   | TEMP/IL       |                |
| APU# / HOURS                        |           | ADDITIONAL UNIT    | START TIME        |           | END TIME          | DRIVER NAME   | DRIVER CONTACT |
|                                     |           |                    | 03/04/2026 055950 |           | 03/04/2026 095331 | Steven Payton | 9132960535     |
| Authorization #                     |           | AUTHORIZATION NAME | PAY TYPE          |           | PO#               | PO ISSUED BY  | DR#            |
| H14011                              |           | JESSIE             | NAB Hankook       |           | H14011            | Marcie        | 0042214        |

COMPLAINT :  
Complaint #1 Trailer- Tire Replacement- Right Front Outside tire on Trailer is Sidewall Damage, Replace with Other LP22.5. Needs a new steel rim, too. [Timothy Haluga - 03/04/2026 06:47] , Right inside the entrance to TA. It's a blue peterbilt [Timothy Haluga - 03/04/2026 06:47]

| DESCRIPTION                          | MECHANIC         | UOM           | QUANTITY                        | LIST PRICE         | PRODUCT                | LABOR                  | EXTENSION |
|--------------------------------------|------------------|---------------|---------------------------------|--------------------|------------------------|------------------------|-----------|
| Tire Replacement                     |                  | EA            | 1.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| HAN3002383 295/75R22.5 TL21 LRG      |                  | EA            | 1.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| FET                                  |                  |               |                                 |                    |                        |                        | 0.00      |
| TIRE DISPOSAL                        |                  | EA            | 1.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| ROADSIDE MILEAGE CHARGE              |                  | EA            | 62.00                           | 0.00               | 0.00                   | 0.00                   | 0.00      |
| SW225X825HW STEEL WHEEL HUB<br>WHITE |                  | EA            | 1.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| ROADSIDE: MECH HOURLY LABOR          | Zachary Justice  | EA            | 3.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| FUEL SURCHARGE                       |                  | EA            | 1.00                            | 0.00               | 0.00                   | 0.00                   | 0.00      |
| Unit :TRAILER                        | Old Brand :OTHER | Position :RFO | Failure Reason :Sidewall Damage | Old Tread Depth :6 | Old DOT# :3AK425411624 | New DOT# :5M0262114025 |           |

|                    |      |
|--------------------|------|
| Parts              | 0.00 |
| Labor              | 0.00 |
| Tires              | 0.00 |
| Fees               | 0.00 |
| Customer Discount* | 0.00 |
| Site Discount      | 0.00 |
| Tax                | 0.00 |



## TOTAL TRUCK CARE

Love's Travel Stops & Country Stores, Inc. D/B/A  
LOVE'S  
0563 St Clairsville, OH SPEEDC  
66320 Belmont-Morristown Rd BELMONT , OH  
(740) 330-6000

INVOICE # : 4009135263  
WORK ORDER DATE : 03/04/2026  
CLOSE DATE : 03/04/2026  
SERVICE TYPE : Roadside

SHIP TO : JS Transportation LLC(3563024)  
9327 Woodend Rd  
Edwardsville , KS 66111-1709  
(913) 422-6657-1

SOLD TO : JS Transportation LLC(3563024)  
9327 Woodend Rd  
Edwardsville , KS 66111-1709

BILL TO : JS TRANSPORTATION LLC(49005761)  
9327 WOODEND ROAD  
KANSAS CITY , KS 66111  
ACCOUNT # : 214701

Total 0.00

\* Customer Discount may include coupons, MLR rewards, and applicable discounts

SERVICE COMMENTS: Driver called in roadcall for bent rim and possibly blown RFO tire on trailer. i called driver before leaving for roadcall to verify location and issue with the unit. i loaded up a tire and rim and left for roadcall. i arrived roadside and had the driver move off of TAs lot over to another parking lot. i took pictures of damages and jacked the trailer up and put it on a jack stand the i removed the RFO tire and rim and replaced with new rim and tire torqued wheel to 475ft/lbs. after letting the trailer down i noticed that the RRO rim was bent i was able to pound it back to shape with a 3 lb sledge. all work is complete at this time... Thank you zsj [Timothy Barnes - 03/04/2026 10:53] , THIS SERVICE REQUIRES RETORQUE OF LUG NUTS AFTER 50-100 MILES OF USAGE. [Timothy Barnes - 03/04/2026 10:53]

Driver Signature :

Service Location: TA at the Dallas pike exit in WV

DID YOU LOVE IT?

Please take a short survey about your experience today:  
Visit [Loves.com/survey](https://Loves.com/survey)

Or Scan the QR Code below:

